

Products: VB370A

Firmware Version: 0.1.1004.16

Published Date: December 15th, 2025

Copyright © 2025



Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed.....	5
Known Issues	5



Revision History and System Requirement

Firmware Version	Region	Date	Model
0.1.1004.16	WW	December 15th, 2025	VB370A
0.1.1002.82	WW	July 4th, 2025	VB370A
0.1.1002.72	WW	March 21st, 2025	VB370A



Important Notice

1. If you need to update to version 0.1.1004.16, please first update to version 0.1.1002.82, and then proceed with the update to 0.1.1004.16
2. The recommended working distance for optimal AI functionality is within 1.5 ~ 5 meters, depending on your setting of camera height and background environment.
3. During system upgrades, please DON'T turn off the power for any reason.
4. If the FW upgrade is not successful, please re-plug power adapter and USB cable to do FW upgrade again.



New Features

Firmware Version	New Features
0.1.1004.16	<ul style="list-style-type: none"> ● Supports SIP and H.323 protocols within AVer Call mode, enabling point-to-point client communication and seamless integration with legacy video conferencing infrastructure and on-premise systems. ● Optimizes the camera tracking algorithm to deliver smoother tracking performance. ● Enables AVer Cloud Management support, allowing IT administrators to remotely monitor device status, manage settings, and perform updates. ● Introduces a scheduled reboot function, permitting users to set specific times for automatic system restarts to maintain optimal performance and stability. ● Extends AI mode support to external cameras within Zoom Room environments, allowing external cameras to utilize intelligent tracking and framing features. ● Assigns the F1 key on the remote control as a dedicated hotkey for Audio Fence AI. ● Support VISCA(IP) protocol camera control in AVer BYOD mode.
0.1.1002.82	<ul style="list-style-type: none"> ● Support AVer BYOD mode. ● Support direct control of VB370A via Room Management (<i>requires Room Management v2.3.1014.0 or later</i>). ● Support 1+5 meeting tiles for multi-stream in Zoom Rooms. ● Support external camera PTZ and preset control in Zoom Rooms. ● Support more VB370A settings via CP10G2 Room Management.
0.1.1002.72	<ul style="list-style-type: none"> ● Support Multi-stream feature in Zoom Rooms (<i>to be available with upcoming Zoom Rooms 6.4.0 update via ZDM, depending on Zoom's release schedule</i>) ● Support Multi-Camera feature in Zoom Rooms. ● Support BYOD feature in Zoom Rooms. ● Removed boot-up notification sound. ● Changed boot-up animation to AVer logo.



Problems Fixed

Firmware Version	Problem Fixed
0.1.1004.16	<ul style="list-style-type: none"> ● Prevents Audio AI features (including Audio Tracking, Presentation Mode, and Audio Frame+) from triggering when the system is muted. ● Resolves an issue where Audio Tracking could become unresponsive or fail to function correctly during prolonged operation. ● Includes various UX and UI enhancements.
0.1.1002.82	<ul style="list-style-type: none"> ● Fixed some UI and UX issues. ● Enhanced system performance.
0.1.1002.72	<ul style="list-style-type: none"> ● Fixed some UI, UX and network issues.

Known Issues

Firmware Version	Description
0.1.1004.16	<ul style="list-style-type: none"> ● SIP/H.323 Compatibility: The following systems and clients have been officially tested and verified for SIP/H.323 functionality (calling, content sharing, and registration): AVer SVC/EVC series: SVC100, SVC500, EVC170, EVC350, EVC950 ; SIP Clients: EZMeetup (mobile/desktop) ● The remote control cannot be used to operate the AVer Call (SIP/H.323) user interface.
0.1.1002.82	<ul style="list-style-type: none"> ● When updating from 0.1.1002.72, manually switch the service provider once via launcher, or perform a factory default, to ensure the web interface works properly.
0.1.1002.72	N/A

