



Products: Room Management for Windows

Software Version: 2.3.1005.0

Published Date: Jan. 07, 2025

Copyright © 2025

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	
New Features	
Problems Fixed	
Known Issues	





Revision History and System Requirement

Software Version	Region	OS	Date	Model
V2.3.1005.0	WW	Windows	Jan. 07, 2025	AVer CAM 、VB 、ProAV Series
				Camera





Important Notice

Room Management is a free software application, succeeding the previous generation PTZApp2. It enables users to control PTZ cameras and videobars, adjust camera image quality, configure AI settings, diagnose operating status, upgrade firmware (automatically or manually), and view live video from the camera. Additionally, it supports speakerphones (FONE series) for feature configuration.

System Requirements

PC Hardware and Software Requirements

- CPU: Intel Core i5-6xxx 3.0GHz

- RAM: 4G

HDD: 3G (Free Space)

- OS: Windows 10 (64 bits), Windows 11(64 bits)

Supported Models

- USB Series:

CAM520 / CAM530 / CAM540 / CAM520 Pro / CAM340 / CAM340+ / VC520 / VC520+ / VC520 Pro / VC322 / VC540 / VB342 / VB342+ / FONE540 / CAM130 / VB130 / CAM550 / VB342Pro / CAM570 / CAM520 Pro3 / VB350 / VC520 Pro3 / FONE700

Virtual Stream function for CAM520 Pro/CAM520 Pro2 / CAM550 / CAM570 / CAM520 Pro3 Virtual Audio function of FONE700

- ProAV Series*:

PTC310HWV2(TR311HWV2) / PTC310UV2(TR313V2) / PTC330UV2(TR333V2) / PTC320UV2(TR323V2) / PTC320UVV2(TR323V2) / PTC320UNV2 (TR323NV2) / PTZ330UVV2 / PTZ330UNV2 / PTZ310UVV2 / PTZ310UNV2 / PTZ231 / PTZ211 / TR211 / TR315 / TR315N / TR335 / TR335N / TR535 / UE1 * PTZApp2 (starting from version 2.2.1002.05) and Room Management (starting from version 2.3.1005.0) support firmware updates and setting functions for ProAV Series cameras..





New Features

Software	New Features				
Version					
	1. Re-branded from PTZApp2 to Room Management.				
	2. Room Management is now a 64-bit application, offering better performance				
	and future scalability.				
	3. Transitioned from a web-based UI to an application-based platform.				
	4. FONE700 enhancements:				
	- Added support for CAM550 Dual Camera for audio tracking, enabling				
2.3.1005.0	seamless dual-camera functionality.				
	- Introduced Microsoft Teams Rooms mode, providing optimized audio				
	performance specifically for Microsoft Teams meetings.				
	- Added a "Strong" option in Reduce Reverberation to enhance control in				
	environments with high reverberation.				
	- Adjusted and refined the user interface for more intuitive tracking				
	settings guidance.				

Problems Fixed

Software Version	Problem Fixed			
2.3.1005.0	1. Resolved the issue where AVer USB VCam was not displaying properly in			
2.3.1003.0	WebEx.			

Known Issues

Software Version	Known Issues	
2.3.1005.0	N/A	

