



Products: PTZApp for Mac OS

Software Version: 1.3.1063.67

Published Date: May 13, 2019

Copyright © 2016

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	. 2
Important Notice	. 3
New Features	. 4
Problems Fixed	. 6
Known Issues	. 7





Revision History and System Requirement

Software Version	Region	os	Date	Model
1.3.1063.67	WW	MAC	May 13, 2019	All USB Camera
1.3.1060.63	WW	MAC	January 28. 2019 All USB Camera	
1.3.1059.60	WW	MAC	November 26, 2018 All USB Camera	
	ww	MAC	October 12,2018	VB342/CAM540/VC 322/
1.3.1052.59				VC520+/CAM520/
				CAM530/CAM340
				VC 322/
1.3.1050.52	WW	MAC	March 16, 2018	VC520+/CAM520/CAM5
				30/CAM340
4.0.4045.40	1404	NAAC	December 07, 0047	VC 322/VC520/CAM520/
1.3.1045.48	WW	MAC	December 27, 2017	CAM530/CAM340
4.0.4004.45		14/14/	VC520/CAM520/	
1.2.1024.45	WW	MAC	August 7, 2017	CAM530/CAM340
1.2.1025.30	WW	MAC	August 5,2016	VC520/CAM520/CAM530
1.2.1021.25	WW	MAC	May 25,2016	VC520/CAM520/CAM530
1.0.1019.21	WW	MAC	January 11,2015	VC520/CAM520/CAM530
1.0.1011.19	WW	MAC	December 14, 2015	VC520/CAM520
1.0.100.11	WW	MAC	September 2,2015	VC520





Important Notice

- 1. PTZ app is a software tool used to configure and upgrade AVer USBCam series
- 2. Supports Mac OS 10.9/10.10/10.11.





New Features

Software Version	New Features				
4.2.4002.07	1. Support CAM340+, FOV 120/FOV 90 degree options				
1.3.1063.67	2. Support VB342+				
	1. Add Smart frame button on PTZapp for CAM540. (Please upgrade CAM540				
	FW to version 0 0 6000.34.)				
	Settings Diagnostic Utility				
	Examing Back Light Control Off				
1.3.1060.63	2. Add "Auto", "Manual" smart frame option for CAM540.				
	Q D Diagnostic Utility				
	Flip				
	ADDR 01 ▼				
	Protocol VISCA VISCA				
	Baud Rate 9600 ▼				
	Smart Framing Manual ▼				
	On Screen Menu Auto				
	1. Add " auto power on/off" option for VB342.				
	2. Add Enable/disable device buttons option for VB342				
	3. Add displaylink enable/disable option for VB342 (While connecting to				
1.3.1059.60	Chrome box, please select "OFF")				
	*To have these new options, please upgrade VB342 FW with version: 0.0.4002.48				





<u>System</u>		
Auto power on	On	•
Enable device buttons	On	•
Displaylink	On	•





Problems Fixed

Software Version	Problem Fixed
1.3.1063.67	None
1.3.1060.63	None
1.3.1059.60	None
1.3.1052.59	None
	Bug fixed.
	1. For Macmini 10.10, when user open PTZApp and connect USB camera, and then
	execute ISP under view seeing environment. It still jump a windows to block ISP.
1.3.1050.52	2. Use VC322 to connect Mac and ZOOM ROOM at the same time. When users
	execute ISP twice, it will jump "Upload file fail" information at the second times.
	Users open PTZApp and Ucam at the same time. When user click auto update at
	PTZApp. It will jump a message "the version doesn't match the devices."
1.3.1045.48	None
	"Upload file failed!" pops-up when performing ISP PTZApp at MAC
4.0.4004.45	10.11.
1.2.1024.45	The device is incompatible with this version! Pops-up when performing
	ISP PTZApp at VC520 at MAC10.11.
1.2.1025.30	None
	"Upload file failed!" pops-up when performing ISP PTZApp under
1.2.1021.25	MAC10.9.
1.0.1019.21	None
	Let PTZ app could record the last setting information on BLC(Back
4.0.4044.40	Light Compensation).
1.0.1011.19	2. Support Multi-Device. (VC520/CAM520)
	3. Support new model.(CAM520)
1.0.100.11	None





Known Issues

Software Version	Known Issues
1.3.1063.67	None
1.3.1060.63	None
1.3.1059.60	None
1.3.1052.59	None
1.3.1050.52	None
1.3.1045.48	None
1.2.1024.45	None
1.2.1025.30	None
1.2.1021.25	None
1.0.1019.21	None
1.0.1011.19	None
1.0.100.11	None
1 2 1052 50	"Upload file failed!" pops-up when performing ISP
1.3.1052.59	PTZApp under MAC10.9.
1 2 1050 52	"Upload file failed!" pops-up when performing ISP
1.3.1050.52	PTZApp under MAC10.9.
1.3.1045.48	None

