



Products: PTZApp for Windows

Software Version: 1.4.1116.123

Published Date: NOV. 26, 2020

Copyright © 2020

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement.....	2
Important Notice	3
New Features	4
Problems Fixed	7
Known Issues	8



Revision History and System Requirement

Software Version	Region	OS	Date	Model
1.4.1116.123	WW	Windows	NOV. 26, 2020	Aver Conference Camera
1.4.1112.116	WW	Windows	June 22, 2020	Aver Conference Camera
1.4.1112.114	WW	Windows	June 05, 2020	Aver Conference Camera
1.4.1103.112	WW	Windows	April 30, 2020	Aver Conference Camera
1.4.1103.108	WW	Windows	March 10, 2020	Aver Conference Camera
1.4.1098.103	WW	Windows	December 13. 2019	Aver Conference Camera
1.4.1091.98	WW	Windows	October 14. 2019	Aver Conference Camera
1.4.1085.91	WW	Windows	September 05. 2019	Aver Conference Camera
1.3.1085.86	WW	Windows	August 08. 2019	Aver Conference Camera
1.3.1075.77	WW	Windows	January 28. 2019	Aver Conference Camera
1.3.1074.75	WW	Windows	November 23,2018	Aver Conference Camera
1.3.1073.74	WW	Windows	October 12,2018	Aver Conference Camera
1.3.1071.73	WW	Windows	September 05, 2018	Aver Conference Camera
1.3.1060.64	WW	Windows	May 5, 2018	Aver Conference Camera
1.3.1054.60	WW	Windows	March 16, 2018	AVer Conference Camera
1.3.1050.54	WW	Windows	November 17, 2017	AVer Conference Camera
1.2.1046.50	WW	Windows	July 26, 2017	AVer Conference Camera
1.2.1034.46	WW	Windows	June 19,2017	AVer Conference Camera
1.2.1034.45	WW	Windows	May 26, 2017	AVer Conference Camera
1.2.1030.32	WW	Windows	August 5, 2016	AVer Conference Camera
1.2.1023.28	WW	Windows	April 8, 2016	AVer Conference Camera
1.0.1021.23	WW	Windows	January 11, 2016	AVer Conference Camera
1.0.1015.21	WW	Windows	November 10, 2015	AVer Conference Camera
1.0.1010.15	WW	Windows	September 2, 2015	AVer Conference Camera






Important Notice




1. PTZApp is a free software and controlling the PTZ Camera, adjusting the camera's image quality, diagnosing operating status, and viewing live video form the camera.
2. PTZApp assists with firmware upgrades
3. Support Operating System of - Windows 7&10. Don't support Windows 8





New Features

Software Version	New Features
1.4.1116.123	<p>1. Support I/O port enable/disable function for VC/CAM520 Pro, CAM540, VB342+.</p> <p>Two options: Enable all ports; Only enable USB port.</p>  <p>2. Support VC/CAM520 Pro to lock/unlock "Set Preset function". While "Off", users can't set preset points via remote control, VISCA command, hotkey or webpage. Please upgrade FW of VC/CAM520 Pro to v.38 or later version to enable this function.</p> 
1.4.1112.116	. None
1.4.1112.114	<p>Support CAM540 to select SmartFrame preset point setting.</p> 
1.4.1103.112	Support FONE540 and Expansion speakerphone setting.



1.4.1103.108	Revised certain Japanese translation sentences.
1.4.1098.103	Support Japanese language and fix some bugs on CAM520 Pro.
1.4.1091.98	<p>1. Support Sleep timer for CAM520/VC520+</p> <p>2. Please update cameras to the newest FW version (v.0.0.0018.36) to support this function.</p> 
1.4.1085.91	<ul style="list-style-type: none"> Support VB342+ audio tracking functions. <p>Notes: Please upgrade VB342+ FW to v.48 to enable audio tracking functions.</p> 
1.3.1085.86	Support CAM540 Smart Frame OFF function. Please go with CAM540 FW. V.0.0.6002.58
1.3.1075.77	<p>1. Add Smart frame button on PTZapp for CAM540. (Please upgrade CAM540 FW to version 0 0 6000.34.)</p>  <p>2. Add "Auto", "Manual" smart frame option for CAM540.</p>



	 <p>The screenshot shows the PTZ Settings menu with options: Flip (Off), ADDR (01), Protocol (VISCA), Baud Rate (9600), Smart Framing (Manual), and On Screen Menu. The 'Smart Framing' option is highlighted with a red box, and its dropdown menu is open, showing 'Manual', 'Manual', and 'Auto' options.</p>
<p>1.3.1074.75</p>	<ol style="list-style-type: none"> 1. Add “ auto power on/off” option for VB342. 2. Add Enable/disable device buttons option for VB342 3. Add displaylink enable/disable option for VB342 (While connecting to Chrome box, please select “OFF”) <p>*To have these new options, please upgrade VB342 FW with version: 0.0.4002.48</p> <p>System</p>  <p>The screenshot shows the System settings menu with three options: Auto power on (On), Enable device buttons (On), and Displaylink (On). Each option has a dropdown menu.</p>
<p>1.3.1071.74</p>	<p>Support flip image setting for CAM540/CAM340/VC322</p>
<p>1.3.1071.73</p>	<ol style="list-style-type: none"> 1. Support CAM540 2. Add DisplayLink driver 3. Add “3.5mm “ description in front of External MIC only & mix in (Phone in jack function). 4. Keep PTZapp always on the top of the PC screen in Windows OS.
<p>1.3.1060.64</p>	<ol style="list-style-type: none"> 1. Support Skype for Business –Far end Camera Control. 2. Add VB342 in support list
<p>1.3.1054.60</p>	<p>None</p>
<p>1.3.1050.54</p>	<p>Add VC322 in support list</p>
<p>1.2.1046.50</p>	<ol style="list-style-type: none"> 1. Support FONE520 AutoTune 2. Add audioDump for VC520. 3. Support VC520+ 4. Add Transfer mode for CAM340
<p>1.2.1034.46</p>	<p>None</p>
<p>1.2.1034.45</p>	<ol style="list-style-type: none"> 1. Support FONE520 & CAM340



Problems Fixed

Software Version	Problem Fixed
1.4.1116.123	None
1.4.1112.116	Fix the bug of VC520 Pro: The PTZApp v.114 has some bugs while operating VC520 Pro.
1.4.1112.114	None
1.4.1103.108	None
1.4.1098.103	Some bugs fixed
1.4.1091.97	None
1.3.1054.60	<p>1. When users who use specific Win7 execute Recovery Tool with CAM340, it pop-up a window "The device is not cam340." (RecoveryTool_1.0.100.11)</p> <p>2. When users who use specific Win7 execute Recovery Tool with VC322, the power adapter is un-plug and re-plug during phase II, it still shows " Please connect to VC322." (RecoveryTool_1.0.100.11)</p> <p>Function and Feature add/modification</p> <p>Check HID is working, before ISP. If HID doesn't work, it will show " update failed warning after ISP. (It occurs on specific PC and use some video software and PTZApp ISP at the same time.)</p>
1.3.1050.54	None
1.2.1046.50	None
1.2.1034.46	Fix FONE520 unable boot issue
1.2.1034.45	None



Known Issues

Software Version	Known Issues
1.4.1116.123	None
1.4.1112.116	None
1.4.1112.114	None
1.4.1103.108	None
1.4.1098.103	None
1.4.1091.97	None

