



Products: FONE700

Firmware Version: 0.0.8300.30

Published Date: Apr. 3rd, 2024

Copyright © 2024

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed	4
Known Issues	4




Revision History and System Requirement

Firmware Version	Region	Date	Model
0.0.8300.30	WW	Apr. 3rd, 2024	FONE700
0.0.8300.24	WW	Jan. 31th, 2024	FONE700
0.0.8300.22	WW	Jan. 12th, 2024	FONE700



Important Notice

1. PTZApp 2 should be upgraded to **v. 2.1.1006.10 (MAC)***; **v. 2.1.1014.17 (Windows)** or later version to get full functions. (*Mac version will be released by 2024/4/30.)
2. During system upgrade, please DON'T turn off the power for any reasons.
3. If the FW upgrading is not success, please re-plug and power adapter and USB cable to do FW upgrade again.
4. To improve system stability, it's required to keep FONE700 Hub, FONE700 Speakerphone, FONE700 Expansion Speakerphone with **the same firmware version**; if there's any difference found, the LED indicator will flash red to remind user to upgrade firmware accordingly.
5. To enable Audio Tracking with CAM550, please connect CAM550 to FONE700 Hub and upgrade **CAM550 to 0.0.8004.24** or later version. **And, please keep the FONE700 and the PC running PTZApp 2 are on the same network.** Please find diagram below:



New Features

Firmware Version	New Features
0.0.8300.30	<ul style="list-style-type: none"> Fulfill UK Product Security and Telecommunications Infrastructure (PSTI) Act 2022 with advanced password mechanism
0.0.8300.24	Enhanced Audio Tracking performance with CAM550
0.0.8300.22	1 st Release

Problems Fixed

Firmware Version	Problem Fixed
0.0.8300.24	Fixed random wake up failure

Known Issues

Firmware Version	Description
N/A	N/A

