

Products: VB370A



Firmware Version: 0.1.1002.72

Published Date: March 21, 2025

Copyright © 2025

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

| | |
|---|---|
| Revision History and System Requirement | 2 |
| Important Notice | 3 |
| New Features | 4 |
| Problems Fixed..... | 5 |
| Known Issues | 5 |



Revision History and System Requirement

| Firmware Version | Region | Date | Model |
|------------------|--------|----------------|--------|
| 0.1.1002.72 | WW | March 21, 2025 | VB370A |



Important Notice

1. The recommended working distance for optimal AI functionality is within 1.5 ~ 5 meters, depending on your setting of camera height and background environment.
2. During system upgrades, please DON'T turn off the power for any reason.
3. If the FW upgrade is not successful, please re-plug power adapter and USB cable to do FW upgrade again.



New Features

| Firmware Version | New Features |
|------------------|---|
| 0.1.1002.72 | <ul style="list-style-type: none">● Support Multi-stream feature in Zoom Rooms (<i>to be available with upcoming Zoom Rooms 6.4.0 update via ZDM, depending on Zoom's release schedule</i>)● Support Multi-Camera feature in Zoom Rooms.● Support BYOD feature in Zoom Rooms.● Removed boot-up notification sound.● Changed boot-up animation to AVer logo. |



Problems Fixed

| Firmware Version | Problem Fixed |
|------------------|---|
| 0.1.1002.72 | <ul style="list-style-type: none">Fixed some UI, UX and network issues. |

Known Issues

| Firmware Version | Description |
|------------------|-------------|
| 0.1.1002.72 | N/A |

