
[Mac] CaptureShare Software Release Note – Aug 9th, 2024

VERSION	1.3.2117.0
HARDWARE	The following product models are supported by CaptureShare.
COMPATIBILITY	Pro AV PTZ Camera:
	 PTZ310/PTZ310N/PTZ330/PTZ330N 0.0.0000.60 and above
	• TR310/TR311/TR311HN/TR313/TR331/TR333 0.0.0000.16 and above
	• TR530/TR320 0.0.1000.47 and above
	 TR333V2/TR323NV2/TR313V2/TR311HWV2 0.1.0000.16and above
	 PTZ310U(N)V2/PTZ330U(N)V2/PTZ211/PTZ231 0.0.0000.12 and later
	• DL30 7.0.0000.08 and above
	• TR535 0.0.0000.18 and later
	• UE1 0.0.0000.09 and later
	Medical Camera:
	 MD330U/MD330UI
	MD120U series
	DocCam:
	• U50/U70/U70+/F17-8M/F50-8M/M17-13M/M15-13M/
OPERATING	M11-8M/M90UHD/M15W/M70W/M5/F50+ Mac 10.15 Mac 11 Mac 12
DEVICES /	IVIAC 10.13 IVIAC 11 IVIAC 12
SYSTEMS	

	T
1.3.2117.0	WHAT'S NEW & Improvement
Release date:	Supports TR535
Aug 9 th , 2024	Supports UE1
	Support offline firmware update
	<u>Features Improvement</u>
	• NA
	KNOWN ISSUES
	• N/A
1.3.2109.0	WHAT'S NEW & Improvement
Release date:	Supports Ukrainian
Dec 11 th , 2023	Supports PTZ211/PTZ231
	Features Improvement
	KNOWN ISSUES
1.3.2099.0	WHAT'S NEW & Improvement
Release date:	Support MD120 series
Aug 17 th , 2023	Support PTZ Camera PTZ310UV2/PTZ310UNV2/PTZ330UV2/PTZ330UNV2
	Features Improvement
	Fix firmware update message of synchronization
	Fix power frequency default value
	Fix some model name cut issue
	Fix AVerMedia BU113 setting empty issue
	Fix USB reconnect detection issue
	TIA OUD TECOTHECT DETECTION ISSUE
	KNOWN ISSUES

1.3.2089.0	WHAT'S NEW & Improvement
Release date: Apr 25 th , 2023	Support PTC330UNV2
	BUG FIXED
	Some UI and wording fixed
	KNOWN ISSUES
	• N/A
1.3.2087.0	WHAT'S NEW & Improvement
Release date:	Support MD330U New Features
Apr 7 th , 2023	Support AVerMedia BU113
	BUG FIXED
	MD330U power off will stop streaming but still can be found from IPCam Utility
	KNOWN ISSUES
	Camera name cut on some long string models.
	Firmware update failure asynchronous
	Power frequency default value error.
	Basic image setting is empty on AVerMedia BU113
	Abnormal UI for 480p or lower streaming format
	USB disconnection retry issue
	No internet connection will randomly cause app no response and show loading.
1.3.2081.0	WHAT'S NEW & Improvement
Release date:	• [New] Support MD330U
Jan 7 th , 2022	



Known Issues	 UVC streaming display isn't workable with <ndi mode="" only="" streaming="">, but users still can select it in the list includes 3rd party Software.</ndi> We are working on the fix for next release. Workaround: Please change the camera mode to "USB only".
	 Camera 4K resolution only can be selected in USB only mode. Workaround: Switch the mode from others to "USB only" mode in web settings.
Limitation	 DL/PTZ/TR camera models don't have the brightness settings in CaptureShare. It can be adjusted in web settings.