



Products: PTZApp 2 for Windows
Software Version: 2.2.1002.05

Published Date: Sept. 26th, 2024

Copyright © 2024

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed	8
Known Issues	9





Revision History and System Requirement

Software Version	Region	os	Date	Model
v2.2.1002.05	WW	Windows	Sept. 26th, 2024	AVer Conference Camera
v2.2.1000.02	WW	Windows	July 18th, 2024	AVer Conference Camera
v2.1.1017.22	WW	Windows	May 31th, 2024	AVer Conference Camera
v2.1.1014.17	WW	Windows	Apr. 3rd, 2024	AVer Conference Camera
v2.1.1012.14	WW	Windows	Feb. 6th, 2024	AVer Conference Camera
v2.1.1000.08	WW	Windows	Nov. 30th, 2023	AVer Conference Camera
v2.0.1056.59	WW	Windows	Nov. 1st, 2023	AVer Conference Camera
v2.0.1055.56	WW	Windows	June 1st, 2023	AVer Conference Camera
v2.0.1053.55	WW	Windows	Mar. 15th, 2023	AVer Conference Camera
v2.0.1051.53	WW	Windows	Jan. 19th, 2023	AVer Conference Camera
v2.0.1044.48	WW	Windows	Oct. 7th, 2022	AVer Conference Camera
v2.0.1043.44	WW	Windows	Sept 13th, 2022	AVer Conference Camera
v2.0.1038.43	WW	Windows	July 1st, 2022	AVer Conference Camera
v2.0.1037.38	WW	Windows	May 3 rd , 2022	AVer Conference Camera
v2.0.1031.37	WW	Windows	April 18 th , 2022	AVer Conference Camera
v2.0.1024.31	WW	Windows	February 14 th , 2022	AVer Conference Camera
v2.0.1019.24	WW	Windows	October 29 th , 2021	AVer Conference Camera
v2.0.1018.19	WW	Windows	August 3 rd , 2021	AVer Conference Camera
v2.0.1016.18	WW	Windows	June 26 th , 2021	AVer Conference Camera
v2.0.1012.16	WW	Windows	April 28, 2021	AVer Conference Camera





Important Notice

- 1. PTZApp 2 is a free software and controlling the PTZ Camera, Videobar, adjusting the camera's image quality, Al setting, diagnosing operating status, Upgrade firmware automatically or manually, and viewing live video form the camera. It also supports Speakerphone (FONE series) for features setting.
- Pairs with EZManager 2 for Remote Grouping Management:
 To simplify device management, you can link PTZApp 2 with EZManager 2. This system categorizes AVer USB cameras (CAM, VB, and VC series) and clearly displays each device's status to make managing your network easy.

System Requirements

PC Hardware and Software Requirements

- CPU: Intel Core i5-6xxx 3.0GHz
- RAM: 4G
- HDD: 3G (Free Space)
- OS: Windows 7 (64 bits), Windows 10 (64 bits), Windows 11(64 bits)

Supported Models

- USB Series:

CAM520 / CAM530 / CAM540 / CAM520 Pro / CAM340 / CAM340+ / VC520 / VC520+ / VC520 Pro / VC322 / VC540 / VB342 / VB342+ / FONE540 / CAM130 / VB130 / CAM550 / VB342Pro / CAM570 / CAM520 Pro3 / VB350 / VC520 Pro3 / FONE700

Virtual Stream function for CAM520 Pro/CAM520 Pro2 / CAM550 / CAM570 / CAM520 Pro3 Only Virtual Audio function of FONE700

*Note: Virtual Camera/Audio now can be used concurrently from 2.2.1002.05

- ProAV Series*:

PTC310HWV2(TR311HWV2) / PTC310UV2(TR313V2) / PTC330UV2(TR333V2) /
PTC320UV2(TR323V2) / PTC320UNV2 (TR323Nv2) / PTZ330UV2 / PTZ330UNV2 / PTZ310UV2 /
PTZ310UNV2 / PTZ231 / PTZ211 / TR211 / TR315 / TR315N / TR335 / TR335N
*ProAV Series features differ from those of the USB Series and currently support **PTZ Control** and **System Information**, effective starting from version 2.2.1002.05





New Features

Software	New Features					
Version						
2.2.1002.05	Support ProAV camera FW update & Setting function					
	2. Optimize FONE700 and CAM550 calibration function and verification process					
	Support ProAV Series camera (please find Support Models section)					
	2. Enable Virtual Cam / Virtual Audio concurrently					
2.2.1000.02	3. Modify Virtual CAM from Directshow to Virtual driver					
2.2.1000.02	– "AVer USB VCAM" is available in Microsoft Teams Rooms					
	4. New setup process for CAM550 and FONE700 Voice Tracking					
	(enabling FONE700 Voice Tracking via CAM550 Preset Link)					
2.1.1017.22	Added 'USB Mode' to the FONE700 to sustain audio tracking functionality when					
2.1.1017.22	connected with the CAM550. (*with the same setup steps)					
	Support VC520 Pro3 new feature setting from PTZApp 2:					
	i. DHCP/Static IP auto-switch setting					
	ii. Smart Gallery Support (PTZApp 2 based)					
	iii. Camera Moving Speed option					
	iv. Preset Link with VC520 Pro3 Speakerphone					
2.1.1014.17	FIZ PTZ Control Reaction Time Set 1 Set 2 VC520 Pro3 Proset Link Proset Link C5 Home C7 VC520 Pro3 C6 Proset Link					
	Support New Product FONE700					
	i. FONE700 Setting					
	ii. Audio Tracking with CAM550* (PTZApp 2 based)					
	*Please find FONE700/CAM550 Release Note for version supported					
	The second secon					
	3. Support CAM570 new feature setting from PTZApp 2:					
	i. Smart Composition					
	ii. Audio Framing+					
	iii. DHCP/Static IP auto-switch setting					
	Support CAM550/CAM520 Pro3/VB342 Pro/VB350 new feature setting from PTZApp 2:					
2.1.1012.14	4. CAM550					
	i. DHCP/Static IP auto-switch setting					





	ii. Preset Link Camera mode			
	5. CAM520 Pro3			
	i. DHCP/Static IP auto-switch setting			
	ii. Preset Link Camera mode			
	iii. Smart Gallery Support (PTZApp 2 based)			
	iv. MT300 Integration Booster			
	6. VB342 Pro			
	i. Auto Frame with ePTZ			
	ii. Audio Frame			
	iii. Audio Tracking Response Speed			
	iv. Audio Tracking Idle Interval			
	v. Reduce Reverberation			
	vi. Object Filter			
	7. VB350			
	i. Audio Framing+ (Two Speakers PIP)			
	ii. Audio Tracking Response Speed			
	iii. Audio Tracking Idle Interval			
	iv. SmartView Shift (Transition Effect) for Al Tracking			
	v. Reduce Reverberation			
	Please find correspond firmware from models respectively, thanks. 1. Support CAM570 (0.0.8102.36) New Feature:			
	i. New option of New Transition Effect (Smart ViewShift Mode)			
	Transition Effect			
	PTZ Movement Smart ViewShift			
	ii. Improved UI of "Conversation Mode"			
	Conversation Mode Trigger Sensitivity			
	4			
	iii. New option of of" Audio Tracking Response Speed"			
2.1.1000.08	Voice Duration Time to Trigger Audio Tracking			
	None 1 sec 2 secs 3 secs 4 secs 5 secs			
	iv. Control (directional pad) and Preset setting improvement			
	2. New Microphone supported for Preset Link:			
	i. Audio Technica ATND1061			
2.0.4050.50	1. Support New Product VC520 Pro3			
2.0.1056.59	2. New Microphone supported for Preset Link:			
	-			






	i. Nureva HDL410
	ii. ClearOne BMA 360
	Support New Product CAM520 Pro3
2.0.1055.56	Support New Product VB350
	Support CAM570 New Feature:
	i. "Conversation Mode Trigger Sensitivity" option
	ii Gaireralian maaa miggar canalimiy apiian
2.0.1053.55	New Microphone supported for Preset Link:
	i. Shure MXA920
	3. Enhance Auto Update stability for firmware update
	1. Support CAM570 New Features:
	ii. Voice Sensor Array Setting
	iii. Camera Moving Speed Option
2.0.1051.53	Support CAM520 Pro2 / VC520 Pro2 New Features:
2.0.1031.33	i. Flicker Decrease Setting
	ii. Keystone Correction
	ii. Reystoric correction
	3. Support Nureva HDL300 / Dual HDL300 for Preset Link
2.0.1044.48	1. Support CAM570 (New Model)
2.0.1044.46	2. Support CAM550 Q3 New Features
	1. Support FONE540 I/O Setting (Please upgrade FONE540 to 0.0.7004.02 or above)
	i. Add "disable all ports except USB" option
2.0.1043.44	ii. Add "line out for sound out" option
	2. Add "new update available" reminder for certain cameras for better experiences
	1. Support CAM550 2022/Q2 Release Features (v0.0.8000.64)
0.0.4000.40	i. Smart Gallery
2.0.1038.43	ii. WDR
	iii. Al Lens Source Detection
2.0.4027.20	Support Yamaha RM-CR Preset Link (Beta) Support CAMEEO Continue Control (analysis by BT7Ann2)
2.0.1037.38	Support AVer VP343Pro pow model
	 Support AVer VB342Pro new model. New function: Keystone Correction and Smart Gallery available for supported models.
2.0.1031.37	2. New function. Reystone Correction and Smart Gallery available for supported models.
2.0.1031.37	USB Devices Virtual Stream Keystone Correction Smart Gallery
	3. Get Yamaha RM-CG, RM-TT supported by Preset Link (Beta).














Problems Fixed

Software Version		Problem Fixed
2.2.1002.05	1.	Fixed FONE700 +CAM550 Audio Tracking positioning setting process
2.1.1017.22	1.	Fixed ClearOne BMA360 connection issue of Preset Link
	2.	Fixed FONE700 Speakerphone alignment process issue





2.1.1014.17	Fixed random green stripe of Virtual Cam
	Fixed PTZ Control with latest CAM570 version
2.1.1012.14	2. Fixed Test Speakerphone feature instability
	3. Fixed no individual installation option for virtual audio
2.1.1000.08	Fixed Yamaha RM-W series connection issue
2.0.1055.56	Fix Preset Link Microphone selection issue
2.0.1051.53	Correct wording of Smart Gallery installation
	2. Fix Virtual Camera (AVer USB VCam) display issue in Teams Client
2.0.1038.43	Fix Sennheiser TCC2 315° Preset Link issue
	2. Enhance firmware upgrade (via PTZApp2) stability
2.0.1012.16	None

Known Issues

Software Version	Known Issues		
2.1.1012.14	Virtual Camera cannot be enabled in Zoom Rooms or Microsoft Teams Rooms		
2.1.1000.08	1.1000.08 Speakerphone Connection UI (linkage) of VC520 Pro3 incomplete		
2.0.1024. 31	Incomplete support for VB342 Pro model. Using this version with VB342 Pro will cause		
	the software to malfunction.		
2.0.1012.24	When PTZApp2 applies for Wan remote pairing invitation for EZManager, if your PC		
	has just switched IP address, please apply after 1 minute.		
2.0.1012.16	None		

