

[Mac] AVerTouch Software Release Note – Aug 05, 2021

VERSION	V1.3.2058
HARDWARE	The following product models are supported by AVerTouch.
COMPATIBILITY	
	M70W(v2) v.5.7.0000.04, M5 v.0.0.0015.16, M15W v5.0.0032.33, M70W v5.1.0038.42,
	M15-13M v5.2.0014.15, M11-8M v6.0.0021.22, M90UHD v5.4.0007.08 or later
	U50, U70, F17-8M, F50-8M, M17-13M
OPERATING	Mac OS 10.14 Mac OS 10.15 Mac OS 11
DEVICES /	
SYSTEMS	
Related Software	Wi-Fi Dongle driver_5.0.9 / Uninstall dongle driver

	WHAT'S NEW & Improvement Google login auto skip Show/hide for password input Improve the camera setting/connection flow to avoid the failure case
	BUG FIXED
V1.3.2058.0	Fixed – AP to Wi-Fi connection failure issue
Release date: Aug 05 2021	Fixed – The Wi-Fi list cannot filter the same SSID name router.
	Fixed – The latency issue for 4K and 1080P display.
	<u>Issues</u>
	If you freeze the camera image and your network is unstable for the camera Wi-Fi connection, the reconnect flow will unfreeze your camera image.
	We are working on the fix for the next release.

Known issues	 Wrong message" fail to change camera information" displays randomly when you setup the camera. Annotation cannot follow the camera image rotate. In google drive library users cannot edit the files, but the file check button is still enabling for user to select.
Limitation	 Cannot set WPA-PSK network in wireless camera. Now we only support WPA2-PSK for wifi setting in AVerTouch. We are working on the additional format includes the WPA-PSK.

- Doesn't support extend display screen now, it can't be recorded and captured.
- Doesn't support Mac OS dark mode. (UI issues happen)
- Sometimes camera cannot be connected that it also is based on your network status.
 Please check your network and reconnect it again.
- Privacy policy and terms of service page pop out the empty webpage if you don't connect to the Internet.