



## AVer UE1 Firmware Release Notes – Mar 28<sup>th</sup> , 2024

<b>VERSION</b>	<b>0.0.0000.17</b>
<b>Camera COMPATIBILITY</b>	<ul style="list-style-type: none"><li>• TR333V2/TR323NV2/TR313V2/TR311HWV2 V0.1.0000.23 and later</li><li>• PTZ310U(N)V2/PTZ330U(N)V2/PTZ211/PTZ231 V0.0.0000.24 and later</li><li>• TR211/TR315(N)/TR335(N) V0.0.0000.24 and later</li><li>• TR535 0.0.0000.18 or later</li><li>• DL30 V7.0.0022.28 or laterTR535 0.0.0000.18 or later</li><li>• CAM550 0.0.8108.04 or later</li><li>• CAM570 0.0.8010.04 or later</li><li>• CAM520Pro3 0.0.9604.04 or later</li></ul>

<p><b>0.0.0000.17</b></p> <p><b>Release date:</b></p> <p><b>Mar 28<sup>th</sup>, 2024</b></p>	<p><b>New Camera</b></p> <ul style="list-style-type: none"> <li>■ Support models: CAM550, CAM570 and CAM520Pro3</li> </ul> <p><b>New Features</b></p> <ul style="list-style-type: none"> <li>■ Automatically adjust the camera Theme mode to Standard/IP mode.</li> <li>■ Add new toggle in RM to enable or disable the forced setting of the Theme mode.</li> </ul> <p><b>Bug Fix</b></p> <ul style="list-style-type: none"> <li>■ N/A</li> </ul> <p><b>Known Issues</b></p> <ul style="list-style-type: none"> <li>■ CAM550/570/520 Pro3 limitation: <ul style="list-style-type: none"> <li>◆ Not support firmware update by Room Management</li> <li>◆ Not support in following modes: PIP/IO Port/AI Lens Streams/Smart Gallery/Smart Composition/Auto Framing</li> <li>◆ Not support setting preset image</li> </ul> </li> </ul>
<p><b>0.0.0000.14</b></p> <p><b>Release date:</b></p> <p><b>Oct 31<sup>th</sup>, 2024</b></p>	<p><b>New Features</b></p> <ul style="list-style-type: none"> <li>■ Support models: PTCv2, PTZV2, TRV3, DL30 and TR535</li> </ul> <p><b>Bug Fix</b></p> <ul style="list-style-type: none"> <li>■ Fix multiple UE1 in LAN crashed issue</li> <li>■ Fix few UE1 boot-up randomly failed issue</li> <li>■ Fix UE1 crashed when USB connected for a long time</li> </ul> <p><b>Known Issues</b></p> <ul style="list-style-type: none"> <li>■ CaptureShare NOT support DL30 ISP firmware update, factory reset, click tracking and tracking preview</li> <li>■ CaptureShare NOT support TR535 Wide-Angle streaming, click tracking and tracking preview</li> </ul>