



AVer Q-SYS Plugin for PTZ Cameras Release Notes - Jul. 21st, 2026

VERSION	V1.1.1011.0
Device Compatibility	The following product models are supported by AVer OBS Plugin for PTZ Cameras. • PTC330/PTC330N/PTC330U 0.0.0000.21 and later • PTC115/PTC500S/PTC115+/PTC500+ 0.0.1000.47 and later • PTZ310/PTZ310N/PTZ330/PTZ330N 0.0.0000.56 and later • PTC310UV2(TR313V2)/PTC310HWV2(TR311HWV2)/PTC320UNV2(TR323V2)/PTC330UV2(TR333V2) V0.1.0000.61 or later • PTZ211/PTZ231/PTZ310UV2/PTZ310UNV2/PTZ330UV2/PTZ330UNV2 0.0.0000.12 and later • TR211/TR315(N)/TR335(N) V0.0.0000.35 and later • TR535(N) V0.0.0000.21 or later • TR615 V0.0.0000.21 or later • TR322 V0.0.0000.06 or later • DL30 V7.0.0022.28 and later • DL10 V7.0.0031.32 and later
Software Requirement	• Q-SYS Designer Software

V1.1.1011.0 Release date: Jul 21st, 2026	New features - Added support for TR322 Improvements - Auto-load IP address, username, and password after application restart Bug fixes - Optimized memory usage for AVerMTControlPanel 1.1.1005.0 in Q-SYS Designer 10.2.0 or later Known issues - Double-click installation of .qplug / .qplugx files is not supported in Designer 10.0 or later version
V1.1.1010.0 Release date: Aug 28, 2025	<u>WHAT'S NEW</u> - Added support for TR535(N) - Added support for TR615 - Added support for camera preview window. - Added support AI Patrol and Framing for supported models - Added support Preset Position setting feature - Added support password masking for enhanced security <u>BUG FIXED</u> - Design crashes after extended period of time <u>KNOWN ISSUES</u> - Double-click installation of .qplug / .qplugx files is not supported in Designer 10.0 or later version
V1.1.1006.0 Release date: Apr 26, 2024	<u>WHAT'S NEW</u> - Support PTZ211/PTZ231 - Support TR211/TR315(N)/TR335(N)

	• Add “Segment” toggle to Tracking Control for specific model. <u>BUG FIXED</u> • Design crashes after extended period of time <u>KNOWN ISSUES</u> • N/A
V1.1.1004.0 Release date: Aug., 2023	<u>WHAT’S NEW</u> • Update Help File <u>BUG FIXED</u> • Serial Number is incomplete with specific model. • Unexpected reconnect while continuous click. • Cannot save camera info. <u>KNOWN ISSUES</u> • N/A
V1.1.1002.0 Release date: May, 2023	<u>WHAT’S NEW</u> • Initial Release to Asset Manager <u>BUG FIXED</u> • None. <u>KNOWN ISSUES</u> • None